






pipe and lines service GmbH

Packer Straße 171, A-8561 Söding

tel. +43(0) 3137/386631, mob.+43(0)664/1328755

reference list

logo	client	country	dim.	project	repair of	year
	OMV Adria Wien Pipeline	Austria	18",16"	crude oil steelpipeline	test rig, int./ext. metal loss, cracks, dents, MAOP uprating of pipes	2011 2012 2013 2015 2016 2017 2018 2019
	RRP-N.V Rotterdam-Rijn pijpleiding Maatschappij	the Netherlands	24"	product steelpipeline	int. metal loss in girth weld, dents, ext. metal loss, weld anomalies	2013 2014 2015 2016 2017 2018 2019
	Transgaz	Romania	16"	steelpipe test rig	ext. metal loss	2013
	SIOT (TAL-Italia) Società italiana per l'Oleodetto Transalpino S.P.A.	Italy	40"	crude oil steelpipeline	dent	2014
	Wintershall	Germany	20"	steelpipe test rig	ext. metal loss	2014

pipe and lines service GmbH

Packer Straße 171, A-8561 Söding
tel. +43(0) 3137/386631, mob.+43(0)664/1328755

reference list







	Wintershall	Germany	5,5"	natural gas steelpipeline	ext. metal loss	2014
	OMV (PLW)	Austria	16"	product steelpipeline	crack-like features in longitudinal weld, dents, ext. Metal loss	2014 2015 2016
	TAL Trans Alpine Pipeline	Austria	40"	crude oil steelpipeline	dents, ext. metal loss	2014 2018
	DOW Olefinverbund GmbH	Germany	6"	ethylen steelpipe	ext. metal loss	2015 2019
	Basell Polyolefine GmbH	Germany	8"	product steelpipeline	ext. metal loss	2016 2017
	Product - Transport Company	Germany	8"	ethylen steelpipe	ext. metal loss	2015
	Gastransport Nord GmbH	Germany	16"	Natural gas	int. Metal loss	2016 2017
	OMV Deutschland GmbH	Germany	12"	crude oil steelpipeline	anomaly , dent anomaly external	2016 2017 2018 2019

pipe and lines service GmbH

Packer Straße 171, A-8561 Söding

tel. +43(0) 3137/386631, mob.+43(0)664/1328755

reference list

	Rhein-Main-Rohrleitungstransportgesellschaft	Germany	20"	product steelpipeline	ext. metal loss, girth weld features	2015 2016
	Stadtwerke München Infrastruktur Region GmbH	Germany	6"	Natural gas	ext. metal loss	2015 2017
	Trans Austria Gasleitung	Germany	42"	Natural gas	ext. metal loss	2015
	Brunsbüttel Ports GmbH	Germany	30"	crude oil	corrosion cluster	2019
	Mineralölverbundleitung GmbH	Germany	28", 20"	crude oil	metal loss, dent, lamination, fabrication feature	2018 2019
	Raffinerie Heide GmbH	Germany	5"	products aromates	metal loss	2018